Ultrasonic Testing Classroom Training Book
Text Corrections (Third Printing)

The following text corrections apply to the third printing of the *Ultrasonic Testing Classroom Training Book.* The fourth printing of this publication has incorporated the corrections into the published text.

Page 14, Figures 2.7 and 2.8: The left-hand diagrams should be labeled "Symmetrical"; the diagrams on the right should be labeled "Asymmetrical." This restores the figures as they appeared in the first printing and is in accordance with the most recent errata for the *NDT Handbook*, third edition: Vol. 7, *Ultrasonic Testing*. The correct figures are shown below:

Figure 2.7: Symmetrical and asymmetrical Lamb waves.



Figure 2.8: Lamb wave modes.



Cat. No. 1642
Third printing with revisions 01/10
Text corrections 06/11